

COMPLETE SAE COUPLING



| Code | Lado bomba | Lado motor |
|------------|----------------------------|---------------|
| HO23208201 | CIL. 19.05 - CH= 4,76 | 3 - 5,5 CV |
| HO23208202 | CIL. 19.05 - CH= 4,76 | 7,5 - 12,5 CV |
| HO23208203 | CIL. 19.05 - CH= 4,75 | 15 - 20 CV |
| HO23310101 | CIL. 22.22 - CH= 4,76/6,35 | 3 - 5,5 CV |
| HO23310102 | CIL. 22.22 - CH= 4,76/6,35 | 7,5 - 12,5 CV |
| HO23310103 | CIL. 22.22 - CH= 4,76/6,35 | 15 - 20 CV |
| HO23310104 | CIL. 22.22 - CH= 4,76/6,35 | 25 - 30 CV |
| HO23310105 | CIL. 22.22 - CH= 4,76/6,35 | 40 CV |
| HO23412702 | CIL. 38.10 - CH= 9,52 | 15 - 20 CV |
| HO23412703 | CIL. 38.10 - CH= 9,52 | 40 CV |
| HO23412704 | CIL. 38.10 - CH= 9,52 | 50 - 60 CV |

The data provided is for guidance only and may be subject to changes or corrections without prior notice. Please contact us if you detect any errors or require further technical information. (Ficha generada el 02/04/2026 a las 13:30:44)